


Case study from Peterborough City Council

Example premise

- New premise with charcoal grill
- Grill and extraction custom made, supplied and fitted by same company
- Initial visit made and questionnaire completed
- Datalogger placed
- Datalogger results show significant CO levels, at times over 500ppm
- No accommodation above



Example premise – monitoring results



Example premise – actions taken

- IN served for substitution or COSHH assessment and appropriate controls
- **Charcoal put out at night** before extraction turned off
- Changes made to extraction to improve efficiency at grill
- Optimum settings determined for extraction, then staff **DO NOT TOUCH**
- Cleaning programme introduced for extraction/ventilation
- Changed grade of charcoal being used? (Debatable value!)
- CO alarm fitted

Example premise – with new controls

